
## **Smart Board Calibration Tutorial**


1. To calibrate your smart board, start off by searching for 'SMART Settings' in your windows search bar on the laptop connected to your smart board.




2. If your smart board is not connected, please select 'Connection Wizard' and begin setup. If it is connected already indicated by a green check mark you can skip to step 8. **SEE NOTE on left.** 

## \*\*\*NOTE\*\*\*


- Please ensure smart display is on and its input is set to the HDMI input you are currently using with your laptop (1 or 2).




3. If smart board is not connected, select next and choose the device name of the smart board.




4. Scroll down and choose 'SMART Board MX-V3 series interactive display' and click next.




5. It may prompt you to check length of cable but it is already set up so select next.




6. It may prompt you to reset cable connection. Follow instructions on prompt.



7. A successful connection will look like the next two steps.



8. The picture below indicates a successful connection. To begin calibration, select 'Orient/Align the SMART product'. You can complete the next step on the smart board itself.



9. Using the smart board pen click each individual calibration point in the center of the target. After you completed that your smart board has been calibrated.

